



Drawn by Richard Hassebrock
8/26/2010

notes:
subject amp had 3 prong cord
installed and all caps replaced

V1 & V3 pins 4&5 to
ground